

# DECKS

Wheelchair access ramp to outside deck area was worn and breaking down.

**BEFORE**



**AFTER**



Two part resin system Coat'N'Sprinkle was applied to the surface by roller coating, while still wet a high grade ceramic material (hardness rating 9.6/10) was sprinkled evenly over the surface, once dry a second resin top coat was applied thus providing sure traction.

# OFFICE STAIRS

Poor lighting and visibility on carpeted stairway become a hazard in an emergency situation.

**BEFORE**



**AFTER**



Black Aluminium cappings were replaced with Glowmate photo luminous cappings. Glowmate provides a clear and visible escape route where smoke, power failures or low-light might otherwise dis-orient workers.

**AUST: Melbourne**

T: +61 3 9798 7450 F: +61 3 9798 7100

**AUST: Sydney**

T: +61 2 9614 1552 F: +61 2 9683 3097

Email: [info@safemate.com.au](mailto:info@safemate.com.au) Web: [www.safemate.com.au](http://www.safemate.com.au)

# WHEEL CHAIR RAMP

Where metal expansion plate joins tiled entrance to ramp, surface of plate becomes slippery when wet.

BEFORE



AFTER



A yellow vinyl backed antislip segment was permanently adhered to plate eliminating slip hazard and highlighting changed surface conditions.

# KITCHEN

Staff were placed in a potential hazardous environment when the vinyl kitchen floor became contaminated with spillage, oil or water.

BEFORE



AFTER



Tough vinyl backed antislip segments were permanently adhered to main walkways thus reducing slip hazard and providing staff with firm footing.